

West Creek Hills

Demolish and Replace Modular Classrooms (WCH)	5.00
New HVAC--MEP (WCH)	4.50
Fix Water on Roof/Masonry; Roof Restoration (WCH)	4.44
Bubbling in Floor (WCH)	4.00
Fix Electrical surge problems and relocate panels (WCH)	3.94
New Fire Doors in gym hallway (WCH)	3.44
Replace Aging Playground Equipment (WCH)	3.33
Additional stroage (WCH)	2.88
Conflicting Bus and Parent Drop off (WCH)	2.75
Increase Paved area of Parking Lot for Events (WCH)	2.19

East Penn Elementary

MEP Systems (EPE)	4.13
New Classrooms and LGI additions (EPE)	3.94
Non-compliant ADA restrooms (EPE)	3.94
New Gym Addition (EPE)	3.81
Lack of Secure Vestibule (EPE)	3.67
Damaged Masonry (EPE)	3.50
Repointed Grout (EPE)	3.13
Undersized Kitchen (EPE)	3.06
Deteriorating Main Entrance (EPE)	3.06
Interior Renovation-wall paint and carpet (EPE)	3.00
Bad acoustics in cafeteria (EPE)	2.81
New elementary admin offices (EPE)	2.69
Insufficient queing for parent drop of (EPE)	2.63

Middle School

MEP Systems (MS)	4.13
Tech Ed classrooms renovations (MS)	4.00
Whole building renovation-bathrooms to classrooms (MS)	3.88
ADA accessibility to internal classrooms (MS)	3.88
Classrooms without natural daylight (MS)	3.38
Undersized chorus room (MS)	3.38
Update create permanent sensory room (MS)	3.38
Limited Flex classrooms and open learning spaces (MS)	3.19
Updating Library Space (MS)	3.13
Undersized Admin offices (MS)	2.53

High School

MEP Systems (HS)	4.19
STEM/Flex classroom addition (HS)	3.94
Updated windows (HS)	3.81
New Band/Chorus addition (HS)	3.63
Dedicated Special Ed Transition Room (HS)	3.31
Permanent updated sensory room (HS)	3.25
Flooring issues (HS)	3.19
brick repointing (HS)	3.06
Conference room space (HS)	3.00
Outdated auditorium finishes (HS)	2.44

KEY:

Green = High Priority/Must Do Items

Yellow = Moderate Priority Items

Blue = Lower Priority/Want to Do Items